ARMY MISSILE COMMAND REOSTONE ARSENAL AL PLANS ANAL--ETC F/G 16/4
MISSILE MATERIEL READINESS REPORTING SYSTEM. EXECUTIVE SUMMARY.(U)
OCT 80 J A BAGGETT, R S DOTSON
DRSMI/D-81-1 NL AD-A096 892 UNCLASSIFIED lor t \$ 16 00 END A-81 DTIC

I



Technical Report D-81-1

MISSILE MATERIEL READINESS REPORTING SYSTEM

EXECUTIVE SUMMARY



OCTOBER 1980



U.S. ARMY MISSILE COMMAND

Redetone Arsenal, Alabama 35505

Approved for Public Release; Distribution Unlimited

Plans, Analysis, and Evaluation Directorate US Army Missile Command Redstone Arsenal, AL 35898

岩

SMI FORM 1021, 1 JUL 79 PREVIOUS EDITION IS OBSOLETE

81 3 26 011

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed. Do not return it to the originator.

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

TRADE NAMES

Use of trade names or manufacturers in this report does not constitute an official endorsement or approval of the use of such commercial hardware or software.

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)


5. Type of Report & PERIOD COVERED Final Report Number Final Report Number Contract or Grant Number(a)
5. TYPE OF REPORT & PERIOD COVERED 9 Final Report 6. PERFORMING ORG. REPORT NUMBER 8. CONTRACT OR GRANT NUMBER(*)
6. PERFORMING ORG. REPORT NUMBER 8. CONTRACT OR GRANT NUMBER(*)
6. PERFORMING ORG. REPORT NUMBER B. CONTRACT OR GRANT NUMBER(a)
B. CONTRACT OR GRANT NUMBER(*)
I/D-82-2
エレローミューユ
10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
AREA & WORK UNIT NUMBERS
12 27 / 1
12. REPORT DATE
// October 3980
13. NUMBER OF PAGES
fice) 15. SECURITY CLASS. (of this report)
Unclassified
15. DECLASSIFICATION/DOWNGRADING
umber)
ess

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)
(Block 20, cont')
DA Form 3266 - Missile Equipment Status Report, used for each reportable failure (Figure 1).
DA Form 3266-1 - Missile Materiel Readiness Report, used for monthly consolidation of DA Form 3266 (Figure 2).
The DA Form 3266-1 serves as the basis for equipment status ratings reported for missile systems designated as pacing items in AR 220-1, Unit Status Reporting
i.

FOREWORD

The Materiel Readiness Reporting System Executive Summary was developed by the US Army Missile Command under the general technical cognizance of Mr. B. J. Risse', Acting Director, Plans, Analysis, and Evaluation Directorate, US Army Missile Command, Redstone Arsenal, AL 35898. AR 750-40, Missile Materiel Readiness Report is the basic document for this Executive Summary.



CONTENTS

Sectio	on	Fage
	ABSTRACT	1
1.	INTRODUCTION	1
2.	OBJECTIVES	1
3.	FOLLOW-ON OBJECTIVES	6
4.	DEVELOPMENT OF EVALUATION PROGRAMS	6
5.	ANALYSIS OF MISSILE READINESS	8
6.	PRESENT OBJECTIVES	15
7.	PERFORMANCE FEEDBACK PROGRAM	15
8.	CONCLUSIONS	15
Q .	DISTRIBUTION	16

ILLUSTRATIONS

Figure		Pa	ge
1. D	DA Form 3626, Missile Equipment Status Report		2
2. n	DA Form 3266-1, Missile Materiel Readiness Report .		3
3. R	Readiness Rating Criteria		5
4. 3	B-Step Readiness/Log Analysis Process		7
5. C	CONUS/World Wide Missile X Status Graph		9
6. T	Theater Missile X Status Graph	. 1	0
7. U	USAREUR (45th AADCOM) Missile X Status	. 1	1
8. E	EUSA/FORSCOM Missile X Status	. 1	2
9. W	Worldwide Missile X Compound Status	. 1	3
ın m	Pheeter Missile Y Component Status	٦),

٧

MISSILE MATERIEL READINESS REPORTING SYSTEM

EXECUTIVE SUMMARY

ABSTRACT

AR 750-40 Missile Materiel Readiness Report prescribes responsibilities and procedures for evaluating and reporting the materiel readiness of missile equipment. Equipment to be reported includes TOE/MTOE systems used for tactical purposes, training equipment, operational readiness float equipment, and selected other missile equipment as directed for a specified purpose and period of time. The reporting system comprises two forms:

DA Form 3266 - Missile Equipment Status Report, used for each reportable failure (Figure 1).

DA Form 3266-1 - Missile Materiel Readiness Report, used for monthly consolidation of DA Form 3266 (Figure 2).

The DA Form 3266-1 serves as the basis for equipment status ratings reported for missile systems designated as pacing items in AR 220-1, Unit Status Reporting.

1. Introduction

The Missile Materiel Readiness Report was developed and introduced in January 1980 to replace the Materiel Readiness Report DA Form 2406. It was important to change from DA Form 2406 because it was a quarterly report and gave no indication as to what specific action was needed to correct degraded readiness conditions in specific units, missile systems, or theaters. A simple system was developed consisting of failure reports (DA Form 3266) which are rolled up into monthly reports (DA Form 3266-1). These reports are key punched as received and form MICOM's readiness evaluation data base.

Objectives

The schedule of objectives for the AR 750-40 reporting system were as follows:

- a. Convert readiness rating criteria from red/amber/green to go no go, design forms, write, staff, and publish AR 750-40 (Aug 78 Dec 79) (Figure 3).
 - b. Establish mechanized AR 750-40 reporting system (Aug 79 Sep 80).
 - c. Initiate AR 750-40 reporting system from field (Big 4 Systems), Jan 80.

	MISSILE EQUIPMENT For use of this form, see AR 750-40.			REQUIRE	EMENT C	ONTROL D-1863	SYMBOL
COMMAN		1 AUTODIN USE ONLY	2. REPORT NO	1 .		(10 15 eo	nmon)
3-1 BN		DIC #A-		WKL			
APO NY		(8) (C)	000076	WK 4		C (16-21 c	ommon)
FROM COMMAN		5 TYPE OF REPORT (22 common)	6 JULIAN 7 WE	APON 8	SYSTEM		
	~~ BN. 57 Th ADA	. WORIGINAL	(23 26 CODI	8,	_ ,	OT MISSI	
APU MY	01473	b. CHANGE	10000	\mathcal{D}		APABLE	
MISSION CAPI)	(3) 34) T		400		(35 38) -
11 END ITEM PCCN C	(45 50)	DATE UULG	NAL (51)	EST I	200	TUAL	(56 59)
LEFETA	450223						
	•	TRAINING C. TELO	DAT d.	TEST			
B OPARTS RE	QUIRED d. ON 1	BLE IN COMMAND? (61 63) HAND IN DS ASL AVAILABLE AT GS (DX)	· D SUBS	LABLE TH	HROUGH S	CONTRO	LLED
c 🗀 ON HA		AVAILABLE THROUGH COMMAND CROSS LEVEL	n. 130 g	ARTS NOT	T AVAIL	ABLE IN	
	GRESS OR COMPLETED 164 661	c END ITEM JOB ORDERE	D	17a N	мсм	b N	MCS
. REPAIR COMP	LETED	(1) To os		SP7	ORG	SPT	OAG
	QUEST CHANGED nge code in item 18b;	, (2: ☐ TO GS (3) ☐ FLOAT	EXCHANGE	(67 69)	(70 72)	(73 75)	176 78,
18a D CHANGE CARD CODE CODE (29)	c DOCUMENT NUMBER (30-43)	d NSN PART NUMBER (44 56)	e. NOUN/MOI	MENCLAT	URE	1 IPD (77 78)	9 QTY 179-80)
01	WK4F6400111001	5960-00-179-4749	ELECTR	T No.	ಗಿಲ	02	01
02 j	, I					į	•
03							
04							
05							} -
19 MALFUNCTION P	EMARKS		-1 -			<u> </u>	
Low V	OLTALE WILL NOT	REEVLATE					
	ED NAME, GRADE, AND BRANCH O	OF AUTHENTICATING OFFICER CPT 4D4	SIGNATURE	Q-5	Zei C.,		
DA FORM 32		FEB 75 IS OBSOLETE	Therm	<u> </u>	/ B	N HQS	1
EN PAREN PE	. • • • • • • • • • • • • • • • • • • •	Figure 1				1COM	3

igure 1 2

UNIT FILE 5

1.70 Pbg., 24 Pbg. 5.74 Abb. 5.84 St. 5.196 F			1.0	- 0 0 0 m	- Contract	10	1.0.1			30	: /. /801	_	(3617, 1861
	<u>-</u>	2 TAGA 1 C 272 7 C 2	Atry C 2/52 ADA HN APC NY 01971	-		y .	ana M	3 ₹ ₹	* 12 de # 4 de #	40.803.43 40.803.43	Volvenfela S A67N		
						-		and the same	V	13 847.61		B MONTH ENDING 15 MRTCh 1980	koika rch 1980
. 12547 2	1.0 % 11.4	Parity avertage Oritical school A A		 		.	:			wwcs 12 ×	•	A Date o	, when 17
MATERIA SALIAN	· • • • •			10 10 10 10 10 10 10 10 10 10 10 10 10 1	ŧ			PERSONAL APARLA MENOLINI	4	SUPPORT		2 PAG	SCPPC BT
OM System PAWE	-		45.4				76.		c,		. 67	† 	5:
	-	•						•	:			• · · · ·	
.	-	•						•			· · ·		
						ı	A1.48.0.384.03	BURTON COMPONENT COMPANY DATA	4				
3	100 00000	TO THE STREET	¥	, 3 , 3	1000	5 P. O.	<u> </u>	2	5 St B.A. '4'	\$4.00 (.4.14	400,386	* ************************************	2000
1 PAR	1,502.3		26.5		*	è	7					-	
							<u> </u>		•	•	•	· -	1
a thibba	1302.00		1.21		χ.	<u>.</u>		-		: 		•	
HILLING.	111	969	Ē		715	· -				•			<u> </u>
,	107 1013	· — ·		_	\$13	7.5	-				• ·	•	
	477985	,	1,64	٠.	· ·	5 2	· ·					•	
#ID: 1	.4022.			- پ		~ ·	٠	. ~	- •				
. •	Hrna6	494		i.	٤.	æ					•		
i	F271750	969	Man - 303	٤	<u>-</u>		<u>-</u>	-					
							•	07					
TO PERFORM PRINCED CANNOT CONSIDER THE CONTRACTOR STATES CAN CAN THE CANNOT CAN	Ala, Co	a Standarder ng an lang	2				 !		IN A VALUE	:	(1) 18 (C)		
A COOK MADE A CO													

Figure _

s END ITEM NOMENCLATURE 1 PAR	SEMIAL NUMBER	C DATE NOT	d DN/GS JOB ORDER NO OR DUCUMENT NO	4 MALFUNCTION OR PART NO
		1	OR DUCUMENT NO	
	-50223	006ti	WK4FG4- 0065-7001	Flectron Tube 5960-00-179-4749
IHIPIR	-50277	0068	W 32NZY -	Tracker I
100	300005	90+0		1430-00-626-8312 Circuit Card
		0032	0047-7003	1430-00-408-2465 Awaiting Shipment to TROED
MSI.	180095	+	N/A	And It is a surplement to them
		•	·	
	i		1	:
	1			
		+		
		+ · · · · · · · · · · · · · · · · · · ·	 	
<u></u>		.		
		•	+	
		•	1	
			<u></u>	
		_		
		1	*	<u> </u>
			•	
	- -	•	+	
		·		·
		•		
L				
		• • • •	- - · · · · · - · · · · · · · · · ·	
13 COMMANDERS READINESS MPACT	STATE WENT			
IPAR failure (Electron T NMC Juring the reporting (Tracker I NSN 1530-00-6 alm-navailability of curc of an IAFL.	(period. Tel 26-8312) also	selerely hax	oth IHIPINS for pered system ca	pahility. The

APPLN01A (0)

READINESS RATING CRITERIA FOR IMPROVED HANK BATTERY (SOMARE)

Report on DA Form	NTOR MISSILE SYSTEM LINES CODED ERC "A"			antities of Equipment o Re On∼Hand and I
3266-1		PCCN	18	
λ	Improved CW Acq Radar (1CWAR)	LEFEDA		SYSTEM RATING INSTRUCTIONS:
x	Improved Pulse Acq Radar (IPAR)	LI FITA	14.	meets the mini am require- ments for all lines shown,
x	Improved High Power IL! Radar (IHPIR)	LEFFBA	1	that system is then con- sidered Mission Cupable
X	Improved Range Only Radar (IROR)	TEFFERA	I _D	(MC). Failure to neet the standard for one or more lines causes the system to
x	Improved Battery Control Central (to include fully op subcomps as listed):	LEFENA	,	he rated Not 1988son Capa- ble (NMC).
	A. Tactical Control Console (TCC)			1. Part must have
	B. CW Tgt Dect Console (CWTDC)		1	either a fully operational ICC or IPCP configured as
	C. Fire Control Console (FCC)			an ICC. B. Unit must have a
	D. Intercom Coord Unit (ICU)		1	fully operational Interrogator Set
х	Information and Coord Central (ICC)(to include fully op subcomps as listed):	LEFELA	1*B	AN/TPY-46(Y) inte- grated into the system
	A. Automatic Data Processor		1AR	C. Data Cable Set will contain as a minimum
x	Interrogator Set AN/TPX-46(V) (IFF)	1F F000	18	10 (3751) 9178555, 6 (3311 10173077, and
x	Data Converter Coord AN/GSA-77 (BTE)	BTEODC	1	1 (35°) 10108181 4 Dato Cabler
X	Improved Platoon Comd Post (IPCP)(to include fully op- subcomponents as listed):	LEFFYA	1AB	D. IPAR and IROR must be operational over 90% of the frequency
	A. Target Display and Engagement Control Console (TDECC)		iv.	hand. F. All launchers must
	B. Automatic Data Processor (ADP)		1A	he cabled to an operational IMPPTR.
X	Improved HAWK Launcher (Lchr)	LUFFCA	3 ^F	
X	Improved Launcher Section Control Box (ILSCB)	LEFEPA		
x	Improved HAWK Missile	LFFFKA	70%	
x	Generator 60KW, 400 Hz	60kWGN	4	
x	Improved HAMK Loader Transporter (Ldr Transp)	THLDFR	1	
X	Cable Assy Set Elec (BIC) AN/GSA-130 (XO-1) consisting of the following	LEFESA		
	A. Power Cables		9	
	B. Data Cables		17	
X	Pallets	TTET\A	11	
<u> </u>	AN/TRC 145	TPCIAS	1 .1	

d. Provide visibility as to Missile Materiel Readiness, Jun 80.

3. Follow-On Objectives

Follow-on objectives were established in July 1980 as follows:

- a. Assess status of AR 750-40 mechanizations, Jul 80.
- b. Develop a set of ADP programs to fully meet mechanization objectives, Jul-Sep 80.
- c. Develop a set of ADP programs to analyze AR 750-40 mechanized output, Aug-Oct 80.


From analysis of the above objectives, a simple three step process has evolved to evaluate readiness. See Figure 4. This process is to:

- a. Manually analyze DA Form 3266-1 to determine system components causing most missile system down time.
- b. From this list of heavy hitters, determine national stock numbers failing most within end items and causing most down time. ARTIS Terminal access to the DA Form 3266 end item failure reports is used for this step.
- c. Prepare multifaceted investigation of specific NSN's to determine recommendations for NICP, NMP, Procurement, Quality Assurance, or design engineering action.

4. Development of Evaluation Programs

In order to facilitate the above evaluation, a number of data evaluation programs have been developed. These programs permit detailed analysis of compiled DA Form 3266. These programs identify the problem by organization, end item, and national stock number of spare parts. In addition, the individual DA Form 3266 data can be displayed in order to check any data entry. The programs shown below can be called up for any time period (i.e., last 30 days, 90 days, or 6 months to one year) if trend analysis is desired.

- a. Failures Selected by Organization
- b. Failures Selected by Weapon System
- c. Failures Selected by End Item
- d. Failures Selected by Mission Identification
- e. Occurrences of NSN by Organization



7

1 ,

REPAIR PARTS

;


COLLING GANYOLS OF MESTS LOGAL THESE TA CASE TO SACREMENT ACTION THESE.

- f. Occurrences of NSN by Weapon System
- g. Occurrences of NSN by End Item
- h. Non-Mission Capable Supply/Non-Mission Capable Maintenance (NMCS/NMCM) or by organization
 - i. NMCS/NMCM by Weapon System
 - j. NMCS/NMCM by Serial Number
 - k. Parts Not Available in Command
 - 1. Individual DA Form 3266
 - m. Any National Stock Number

5. Analysis of Missile Readiness

- a. Figures 5 through 8 are examples of the materiel readiness of Missile System X for a typical month. From this analysis, overall trends in readiness performance of the missile system worldwide down to theater, command, and battalion level can be identified. Notational data is used to preclude classification of this paper.
- b. Figures 9 and 10 show the components causing Missile System X's downtime both worldwide and by theater. Since Radar Y is consistently causing most of the system downtime, an analysis of all failure reports submitted on this radar is called up on the ARTIS Terminal and printed out. The analysis of the printout shows that the Liquid Cooler (NSN 1430-00-066-5696, AMDF price \$16,064.00 each) is the heavy hitter item most often reflected in the failure reports. The demand history for this stock number is then called up on the ARTIS Terminal and printed out. The demand history analysis shows that 182 Liquid Coolers have been issued in the past 24 months to support Radar Y's total density of 80 each. This means that on the average the Liquid Cooler is being replaced once a year or slightly more often. Further inquiry reveals the 2 Bn sample data collection mean time between failure rate is one Cooler failure every 3.5 months, most of which are repaired with piece parts at the DS level. Ultimately, two needed fixes are identified. One involves rerouting a wiring harness to prevent it from rubbing against the vibrating pump and wearing through the wiring insulation causing an electrical short and possible fire. The other involves a better oil coolant pressure leak test at the contractor's cooler rebuild shop to stop field rejections of rebuilt coolers for leaking coolant seals, hoses, etc.
- c. Follow-up procedures are needed to insure that the specified corrective actions are in fact accomplished. Currently, a review of "old business" and status of these actions is accomplished before the start of the monthly MICOM readiness review for the DCG Readiness, Project Managers, and Directors. The objective is to get well on the problem-causing repair parts, thus improving the readiness of the heavy hitter component end item and thereby improve the total missile system material readiness performance.

UNCLASSIFIED
MISSILE SYSTEM X



UNCLASSIFIED
Figure 5




Figure 6

10


UNCLASSIFIED
MISSILE SYSTEM X

		α α α α α		6/51
		% 8 0 1		3/55
(3266-1)		20 60 7		2/61
1		2/5/2/ 2/5/2/		2/54
READINESS REPORTS		0 8 + B		3/6
EADINE		6.80 4 V		3/61
SYSTEM R		W E A W		2
		N TO TO		2/3
# MISSILE	C C C C C C C C C C	MCS NACS		
LINI	USAREUR (45TH ARDCOM) MC NMCS NMCM 84 6 18	~		
) 	NACS (45)	SYSTEM		
	LISARE TC BA	S. RVAII		
			or some a survey comment of discovers and discovers	

UNCLASSIFIED

Figure 7

UNGLESSIFIED
MISSILE SYSTEM X




UNCLASSIFIED
Figure 8

Figure 9

UNCLASSIFIED
MISSILE SYSTEM X
COMPONENTS CAUSING SYSTEM NMC TIME
BY THEATER

•



UNCLASSIFIED

Figure 10

6. Present Objectives

The current objectives are to refine our readiness and logistical analysis procedures and establish realistic readiness yardsticks for future systems. This will be done by threat analysis, development of missile system hardware matrices, and assignment of rating criteria in coordination with the field missile community, Project Manager personnel, TRADOC schools, and DA staff. The immediate objectives are to:

- a. Compile historical records Lessons Learned.
- b. Analyze data records for remedial actions needed.
- c. Use data analysis to effect timely feedback to user.
- d. Maintain coordination between MICOM support elements and field commanders.

7. Performance Feedback Program

In conjunction with actions as outlined in Para 6 above, a user feedback program is being implemented in three phases. In Phase 1, as a product of our repair parts expediting effort, we began in January 1980 to provide daily feedback to field requisitioners on status of requisitions for repair parts reported as required on the DA Form 3266 failure reports. In Phase 2, beginning in May of this year, a program of data feedback to the field commanders was initiated. This program consists of providing detailed analysis of weapon system and missile unit material readiness performance in color transparency form on a monthly basis. Starting at MACOM level, we now plan to go down to division level by December. Field response to this program has been rapid and very positive.

In Phase 3, between now and February 1981, we expect to have established a mail order catalog of selected computer printouts. These printouts will show the failure history of a unit, a missile system, and end items to include repair parts for each failure. These reports will be made available to commanders down to battalion level on a request basis.

8. Conclusion

The objective of the Missile Materiel Readiness Reporting System was originally to provide the Commander, MICOM, with visibility as to specific causes for degraded missile materiel readiness in the most timely manner feasible. In addition, continuing efforts have been implemented which provide the capability to analyze the field reports and initiate timely remedial action. The field commander can now be apprised of the status of his missile readiness in comparison with his contemporaries and of positive action being taken by support agencies to improve his readiness posture as well as an indication of those actions he can take locally to help himself.

DISTRIBUTION

	No. of	Copies
Commander US Army Materiel Development and Readiness Command ATTN: DRCPA-SA 5001 Eisenhower Ave. Alexandria, VA 22333	1	
Director US Army Materiel Systems Analysis Activity ATTN: DRXSY-DL/DRXSY-C Aberdeen Proving Ground, MD 21005	1	
Jommander US Army, Harry Diamond Laboratories ATTN: DELHD - Sys Anal Washington, DC 20438	1	
Commander US Army Troop Support and Aviation Materiel Readiness Command ATTN: DRSTS-G 4300 Goodfellow Boulevard St. Louis, MO 63166	1	
Commander US Army Communications and Electronics Materiel Readiness Command ATTN: DRSEL-SA Fort Monmouth, NJ 07703	1	
Commander US Army Tank Automotive R&D Command ATTN: DRDTA-RPL Warren, MI 48090	1	
Commander US Army Tank Automotive R&D Command ATTN: DRDTA-V Warren, MI 48090	1	
Commander US Army Armament Readiness Command ATTN: DRSAR-SA Rock Island, IL 61201	1	

	No. of Copies
Commander US Army Armament R&D Command ATTN: DRDAR-SEA Picatinny Arsenal Dover, NJ 67801	1
Commander US Army Depot Support Command ATTN: DRSTS-MC Letterkenny Army Depot Chambersburg, PA 17201	1
Commander US Army Mobility Equipment Command ATTN: DRDME-0 Fort Belvoir, VA 22060	1
Commander Natick Research & Development Command ATTN: DRXNM-O Natick, MA 01760	1
Commander US Army Test and Evaluation Command ATTN: DRSTE-SY Aberdeen, MD 21005	1
Commander US Army International Logistics Command ATTN: DRSIL-WS Alexandria, VA 22333	1
Director MUCOM Operations Research Group Edgewood Arsenal, MD 21010	1
DRC Inventory Research Office Hoom 800, US Custom House Second and Chestnut Streets Philaielphia, PA 1919	2
I mmander US Army TRADOC Systems Analysis Astivity ATTN: ATAA-TBB White Canic Missile Bruse, NM (2004)	1
Commander O Army o foregoe Analysis Androy Di Wordmont Arms Betroods MT (1904)	1

	No. of Copies
Commander US Army Logistics Management Center ATTN: DRXMC-D Ft. Lee, VA 23801	1
Defense Documentation Center Cameron Station Alexandria, VA 22314	1
Commander US Army Research Office P.O. Box 12211 Research Triangle Park, NC 27709	1
Commander DARCOM Automated Logistics Management Systems Activity 210 N. 12th Blvd P.O. Box 1578 St. Louis, MO 63188	1
Commander US Army Aviation R&D Command ATTN: DRDAV-D P.O. Box 209 St. Louis, MO 63166	1
Commander US Army Communications R&D Command ATTN: DRDCO-SA Ft. Monmouth, NJ 07703	1
Commander DARCOM Materiel Readiness Support Activity ATTN: DRXMD-EI Bluegrass Army Depot Lexington, KY 40511	1
Commander US Army Electronics R&D Command ATTN: DRDEL-SA Adelphi, MD 20783	1
Commander Logistics Management Center ATTN: DRXMC - Log Anal Ft. Lee, VA 23801	1
Commander US Army Tank Automotive Materiel Readiness Command ATTN: DRSTA Warren, MI 48090	1

	Ke. of	Copies
Commander USA CSLA ATTN: SFLCL-NMP-ME Ft. Huschuca, AZ 85613	Ĩ	
Commander US Army Logistics Evaluation Agency ATTN: DALO-LEA New Cumberland Army Depot New Cumberland, PA 17070	2	
Commander US Army Forces Command ATTN: AFLG-RE (COL Fertain) Ft. McPherson, GA 50330	3	
Headquarters Department of the Army ATTN: DAMO-ODR (LTC Daum) The Pentagon Washington, DC 20310	Ĩ	
Headquarters Lepartment of the Army ATTN: DALO-PLR (Mr. Kelley) The Pentagon Washington, DC 20310	7 -	
Major General Charles F. Means Commanding General 32d Army Air Defense Command APO New York 09175	7	
Commandant US Army Air Defense School AITN: ATSA-CD-MS-M (Mr. Vaughn) Et. Bliss, TX 79916	-	
Commander 36th Artillery Brigade ATTN: EAAB-LO APO San Francises 90576	2	
Jommander Sth US Army ATTN: DJ-MS-MC (Mr. Wade, J4) APO San Francisco 96301	1	

	No. 01	Copies
Commander	1	
US Army Materiel Development and Readiness Command		
ATTN: DRCRE-FS (Mr. Driscol)		
5001 Eisenhower Ave.		
Alexandria, VA 22333		
Commandant	1	
US Army Field Artillery School		
GM Section		
ATTN: ATSF-WD-GM (LTC Hallaque)		
Commander	1	
US Army Research and Stdrd Group (Europe)		
Edison House		
223 Old Mary Lebone		
London NWI, 5th UK		
Box 65 FPO, NY 09510		
DRSMI-FR, Mr. Strickland	1	
-LP, Mr. Voig	1	
- C	1	
DRSMI-X	1	
-RPR	2	
-RPT (Record Set)	2	
(Reference Copy)	1	
$_{-}$ 7 σ	5	

